



UniquePolymerSystems.com

The Engineer's Choice

... for Solutions

Providing Low Cost Solutions
To High Cost Problems

UPS 6644 Conveyor Belt Repair Kit

Conveyor belts can suffer from a multitude of problems due to the damage / wear that is caused especially in abrasive situations.

Belt surfaces can become ripped and suffer from abrasive damage that in turn can affect the performance and reliability.

If the belt becomes clogged this can cause further severe problems.

Generally a change of a belt involves high costs – Price of a new belt, long downtimes (from 16 – 20 hours) depending on the equipment conditions, etc. the selection of a non-appropriate product, for instance, a product that has different hardness from the original belt causes loosening of material when going through a driving pulley and conducted to the little flexibility.

The Unique Polymer Systems UPS 6644 Conveyor Belt Repair kit contains most products you need to make a Quick and Effective in-situ repair.

UPS 6644 Conveyor Belt Repair Kit Contents:

- 4 X 1kg UPS 80 XRG
- 5 X 1 Roll UPS TBRT 4
- 1 X 5lt UPS TAC 883 Universal Cleaner
- 5 X 100ml UPS TAC 075 Primer
- 5 X 5ml UPS FTFC Catalyst
- 5 X 100ml UPS TAC 872 Release Agent
- 1 X UPS ARB
- 2 X Roll UPS Masking Tape
- 10 X Pair Gloves
- 1 X Specifically Designed Tool Box



Video Application Guides And More Available On YouTube – Just Visit www.youtube.com & Search Unique Polymer Systems TV

Unique Polymer Systems Ltd, Unit 1, Bankside Industrial Estate, Ledbury, HR8 2DR
+44 (0) 1531 636 300 • info@uniquepolymersystems.com • www.uniquepolymersystems.com



Application Procedures



1. Typical Belt With Fastener



5. Apply The UPS TAC 075 Primer



2. Surface Preparation - Abrasive Brush



6. Apply UPS 80 XRG



3. Cleaning With UPS TAC 883



1. Joint Tape In Place



7. Finished Products in *Less Than 10 Minutes!*

Video Application Guides And More Available On YouTube – Just Visit www.youtube.com & Search Unique Polymer Systems TV